

APPLIED MANUFACTURING RESEARCH

DEPARTMENT 190-2

EVALUATION OF NEW MANUFACTURING PROCESSES

AND TECHNIQUES

FINAL REPORT

PR 927

w.o. 27093

January 1961

Distribution of this document is unlimited.

L. 7/ Mattek
Mfg. Development Engineer

Approved by:

Dr. 3. L. Armi, Chief

Applied Mfg. Research

Group Enginee:

Concurrence:

R. M. Hatcher, Manager Applied Mfg. Fesearch,

Operating Controls and

Methods


CONVAIR

A Division of General Dymamics Corporation

(lan Diego)

CONVAIR-ASTRONAUTICS MAR 13 1961

Ŋ.



EVALUATION OF NEW MANUFACTURING PROCESSES AND TECHNIQUES

ABSTRACT

A number of Convair-San Diego production problems are outlined. Facilities which were investigated in an effort to solve the problems are listed with the evaluation and action taken by Convair.

ACCESS HAT	· Al				
0F3 11	n. 1 s.s on 25				
306	SOLF SESTION				
Bir V 480 (Birl	·· .				
HOSTIF HOATION					
117 21573196	TOR AVAILABILITY COULT				
BIST.	AVAIL ME M SPERIAL				
į					
} -	1				
1	- !'				

Cost of project: \$6,500.00 (Estimate)

Convair-San Diego

TABLE OF CONTENTS

1. Project Title 1 2. Statement of Problem 1 3. Objective 1 4. Purpose 1 5. Conclusions and Recommendations 1 6. Development of Project 1 6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 1 6.2 Problem: Burrs are difficult to remove from inaccessible small passageways and internal blind holes. 2 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 3 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality enceptoded. 3 6.5 Problem: No successful technique for brazing moneycome sandwich panels has been develored at Convair-San Diego. 6 6.6 Problem: The quenching hase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightful for use. 5 6.7 Problem: Secent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convair development. 12 6.8 Groblem: The Youak Masking Process cans not been collaboration in the single energy forming development. 13 6.9 Groblem: The Youak Masking Process cans not been collaboration in the single energy forming development. 14 6.9 Groblem: The Youak Masking Process cans not been collaboration as implement characterical all lines at Convair-san Technical and Convair-san Techni	PARA.		SUBJECT	PAGE
3. Objective 4. Purpose 5. Conclusions and Recommendations 6. Development of Project 6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 6.2 Problem: Burns are difficult to remove from inaccessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality encyproduct. 6.5 Problem: No successful technique for brazing honey-come sandwich panels has been nevelored at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straintingly on some parts to make them acceptable for use. 6.7 Problem: Recent developments in the bleft energy forming field at Fort North have not been assimilated to supplement Convair-San Diego's high energy forming development. 6.8 Problem: The Kousk Masking Process ons not been evaluated as a possible capital investment to supplement Convair-Conv	1.	Project Title		1
4. Purpose 5. Conclusions and Recommendations 6. Development of Project 6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 6.2 Problem: Burns are difficult to remove from inaccessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality encorance. 7.5 Problem: No successful technique for brazing namey-come sandwich panels has been nevelow at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightful. on some parts to make them acceptable for use. 7.7 Problem: Recent developments in the high captry forming field at Fort North have not been assimilated to supplement Convair-San Diego's high energy forming development. 7.8 Problem: The Kodak Masking Process one not been caluated as a possible capital investment to supplement changed and forman-	2.	Statement of	Problem	1
5. Conclusions and Recommendations 6. Development of Project 6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 6.2 Problem: Burns are difficult to remove from inaccessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality entry product. 6.5 Problem: No successful technique for brazing noneycome sandwich panels has been nevelowed at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightful. For on some parts to make them accordable for use. 6.7 Problem: Fecent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convair-San Diego's high energy forming development. 6.8 Froblem: The Kodak Masking Process cas not trem caluated as a possible capital investment to supplement decided allives at Convair-	3.	Objective		1
6. Development of Project 6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 6.2 Problem: Burrs are difficult to remove from inaccessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality encountered at Convair-San Diego. 6.5 Problem: No successful technique for trazing money-come sandwich panels has been nevelone at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straighted. To on some parts to make them acceptable for use. 6.7 Problem: Recent developments in the high energy forming field at Fort North have not been assimilated to supplement Convair-San Diego's high energy forming development.	4.	Purpose		1
6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 6.2 Problem: Burrs are difficult to remove from inaccessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality enterproduct. 6.5 Problem: No successful technique for brazing noneycome sandwich panels has been nevelow at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heattreatment causes erratic distortion which necessitates extensive hand straightful. On some parts to make then acceptable for use. 6.7 Problem: Secent developments in the high energy forming field at Fort Morth have not been assimilated to supplement Convair-San Diego's high energy forming development. 6.8 Problem: The Youak Masking Process as not been evaluated as a possible capital investment to supplement chemical all'inc at Convair-	5.	Conclusions a	nd Recommendations	1
frequently encountered on barrel finished parts that have been hand dried by forced air blowing. 6.2 Problem: Burrs are difficult to remove from inaccessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality encorate. 6.5 Problem: No successful technique for brazing noneycome sandwich panels has been revelowed at Convair-San Diego. 6.5 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straighted, on some parts to make them acceptable for use. 6.7 Problem: Recent developments in the block energy forming field at Fort North have not been assimilated to supplement Convair-San Diego's high energy forming development. 6.6 Problem: The Kodak Masking Process has not been evaluated as a possible capital investment to supplement chemical all the at Contair-	6.	Development of Project		1
cessible small passageways and internal blind holes. 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality emproduct. 6.5 Problem: No successful technique for brazing noney-come sandwich panels has been nevelone at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightful consome parts to make them acceptable for use. 6.7 Problem: Recent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convair-San Diego's high energy forming development. 7.8 Problem: The Kodak Masking Process has not been challed as a possible capital investment to supplement themical cilling at Convair-		6.1 Problem:	frequently encountered on barrel finished parts that have been hand dried by forced	1
in thin walled high strength tubing. 6.4 Problem: Excessive hand finishing of detail parts leads to a high-cost low-quality end product. 6.5 Problem: No successful technique for brazing noney-come sandwich panels has been nevelone at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightend; on some parts to make them acceptable for use. 6.7 Problem: Fecent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convair-San Diego's high energy forming development. 6.8 Problem: The Kodak Masking Process has not been calculated as a possible capital investment to supplement chanical alliers at Convair-		6.2 Problem:	cessible small passageways and internal	2
leads to a high-cost low-quality end product. 3 6.5 Problem: No successful technique for brazing noney-come sandwich panels has been newelow at Convair-San Diego. 6.5 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightend; on some parts to make them acceptable for use. 6.7 Problem: Recent developments in the high energy forming field at Fort Morth have not been assimilated to supplement Convair-San Diego's high energy forming development. 7.8 Problem: The Kodak Masking Process has not been evaluated as a possible capital investment to supplement chanical will be at Convair-		6.3 Problem:		3
come sandwich panels has been nevelore at Convair-San Diego. 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightend; on some parts to make them acceptable for use. 6.7 Problem: Tecent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convair-San Diego's high energy forming development. 6.8 Problem: The Kodak Masking Process has not been evaluated as a possible capital investment to supplement chemical cilling at Convair-		6.4 Problem:	leads to a high-cost low-quality end	3
treatment causes erratic distortion which necessitates extensive hand straightens, to on some parts to make them acceptable for use. 5.7 Problem: Fecent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convair-San Diego's high energy forming development. 5.8 Problem: The Kodak Masking Process has not been evaluated as a possible capital investment to supplement chemical Allier at Convair-		6.5 Problem:	come sandwich panels has been develore	ت
forming field at Fort Worth have not here assimilated to supplement Convair-San Diego's high energy forming development. 7. Problem: The Kodak Masking Process cas not been evaluated as a possible capital investment to supplement chemical will be at Convair-		ό.ό Problem:	treatment causes erratic distortion which necessitates extensive hand straighten. To on some parts to make them acceptable for	
evaluateu as a possible capital investment to supplement chemical will limit at Convair-		o.7 Problem:	forming field at Fort Worth have not been assimilated to supplement Convair-San	
		√. ^a Froblem:	evaluateu as a possible capital investment	11

. . .

Convair-San Diego

TABLE OF CONTENTS

PARA.		SUBJECT	PAGE
	6.9 Problem:	Convair-San Diego has not utilized the	
		solutions of industry-wide problems pre-	
		sented at Technical Society Conventions.	12
i.	Bibliography		14

Convair-San Diego

1. PROJECT TITLE: Evaluation of New Manufacturing Processes and Techniques.

2. STATEMENT OF PROBLEM:

The results of millions of dollars spent annually by the Government and the airframe industry in developing new manufacturing processes and techniques are not always reported, or if so, not analysed in time to effect utilization in current programs at Convair-San Diego.

3. OBJECTIVE:

- (1) To investigate latest techniques and facilities used by other manufacturers in the solution of selected current or potential production problems.
- (2) To set up a controlled experiment, if necessary, to varify the results of investigations and to incorporate beneficial results into production or future planning.

4. PURPOSE:

To take early advantages of manufacturing improvements, avoid duplication of efforts and reduce costs.

5. CONCLUSION AND RECOMMENDATION:

See paragraph 6 for the evaluation and action taken on each problem.

6. DEVELOPMENT OF PROJECT:

6.1 Problem: In our present practice, corrosion is frequently encountered on barrel finished parts that have been hand dried by forced air blowing.

6.1.1 Facilities Investigated: (Ref. 7.1)

(1) A heated barrel type rotary drier with corn husk and cob drying powder - Convair-Pomona.

- 6.1.1 Facilities Investigated: (Cont'd)
 - (2) A heated barrel type rotary drier with saw dust drying media. Colormatic Sales Co., Gardena, California.
- 6.1.2 Evaluation: The heated barrel type rotary drier, using either saw dust or corn cob drying compounds, eliminates the corrosion problem.
- 6.1.3 Action Taken: A written recommendation was submitted to Department 8, to request a heated rotary drying unit for Department 115 Capital Budget. The recommendation was in support of a Department 115 request.
- 6.2 <u>Problem</u>: Burrs are difficult to remove from inaccessible small passageways and internal blind holes.
 - 6.2.1 Facilities Investigated: (Ref. 7.1)
 - (1) Dynamic Internal Hone Designed and developed by Convair-Pomona.
 - (2) "Back-burring" machine at Convair-Pomona.
 - 5.2.2 Evaluation: Both machines perform satisfactorily, but

 Dynamic Internal Hone is applicable to almost all tasks,

 while "back-burring" is applicable essentially to drilled holes.
 - 6.2.3 Action Taken: Convair-Jan Diego, at present, does not have enough applications to warrant capital expenditure.

 If and when demand supports procurement, the Dynamic Internal Hone is recommended for versatility advantages.

- 6. **DEVELOPMENT OF PROJECT:** (Cont'd)
 - 6.3 Problem: Convair is unable to make 2D or less bends in thin walled high strength tubing.
 - 6.3.1 Facilities Investigated: (Ref. 7.2)
 - (1) Kilsby Tube Supply Los Angeles.
 - (2) Aeroquip Mfg. Corporation Los Angeles.
 - 6.3.2 Evaluation: Bending of high strength tubing has not been sufficiently developed at the facilities investigated. However, a unique method of bending 1 inch diameter aluminum tubing to 2 inch diameter bends, using rubber mandrels, was inspected.
 - 6.3.3 Action Taken: A Project Request is in preparation to evaluate the rubber mandrel method of bending aluminum.
 - 6.4 <u>Problem</u>: Excessive hand finishing of detail parts lends to a high-cost, low-quality end product.
 - 6.4.1 Facilities Investigated: (Ref. 7.3)

 The Fort Worth facility has expended considerable effort on this problem. A trip was, therefore, made to observe and evaluate the work accomplished by their program.
 - 5.4.2 Evaluation: Fort Worth attacked the problem in three steps, as follows:
 - (1) Surveyed all hand finish operations and then acquainted the factory inspection, tooling and engineering personnel with their findings.
 - (2) Engineering reviewed all drawings for consistency of finish and deburring requirements, and then determined

6.4.2 Evaluation: (Cont'd)

- (2) whether all requirements were necessary and realistic.

 Planning reviewed operational planning and determined whether all deburr operations were really necessary in order to reflect engineering requirements.
- (3) The third course of action was to determine and put to use the most economical method of deburring, breaking corners or blending, consistent with requirements and peculiarities of each part. Present methods of deburring and blending are as follows:

Barrel finish Sand blast
Chemical etch Hand finish and hand deburr.

Fort Worth makes every effort to use barrel finish

After analyzing corner breaks of 0.015" as specified by Engineering drawing, Fort Worth allowed corner breaks of 0.005" to 0.025", which would be within a drawing tolerance of \$\notineq\$ 0.010". A three minute immersion of aluminum parts in a chemical etch solution would produce a 0.005" corner break. Chemical etch also performed satisfactorily for blending machined surfaces. Large machined aluminum bulkheads, spar caps and machined fittings of all kinds were satisfactorily deburred by chemical etch.

Sandblast deburring did not prove satisfactory in most cases.

4

to the fullest extent.

6. DEVELOPMENT OF PROJECT: (Cont'd)

6.4.3 Action Taken:

- (1) A similar attack to that employed by Fort Worth is being conducted at the San Diego Division in reducing deburring costs. A reduction of 6 men in the deburring area has been effected by substituting barrel finishing.
- (2) Additional equipment, including a heated barrel tumbler drier and a mechanical belt sanding machine, has been included in the 1961 Capital Budget.
- (3) Continuing coordination with Fort Worth was scheduled to take mutual advantages of the developments of both Divisions.
- 5.5 Problem: No successful technique for brazing honeycomb sandwich panels has been developed at Convair-San Diego.
 - O.5.1 Facility Investigated: (Ref. 7.3)

 An electric blanket brazing process at Const.r-Fortulation.
 - b.5.2 Evaluation: An excellent curved production partials been brazed by this method in the Fort Worth pilot shop. The arrangement consists of a Glasrock reference plane tool on one side only, strip heaters, the Fort forth Famer type braze box, a steel air pressure bar and a restraining cover. To accelerate cool down, an air charter of masonite was bonded to the lower side

- of the Glasrock reference plane, which had air passages through the tool to grooves on the face next to the braze box. A relatively inexpensive electrical power supply and control is required to operate brazing sys-
- 6.5.3 Action Taken: Fort Worth report #FMR 4-251 was obtained and submitted for further evaluation, for possible future applications.
- 6.6 Problem: The quenching phase of aluminum heat-treatment causes erratic distortion which necessitates extensive hand straightening on some parts to make them acceptable for use.
 - 6.6.1 Facilities Investigated: (Ref. 7.4)

tems of this type.

The following aluminum heat-treat facilities were visited:

Ryan Aeronautical Corporation - San Diego
Rohr Aircraft - Chula Vista
Lockheed Aircraft - Burbank
Production Heat-treating Co. - Hollywood
North American Aviation - El Segundo
Douglas Aircraft - El Segundo
Quality Aluminum Heat-treating Co. - El Segundo
South. Calif. Aluminum Heat-treating Co. - Vernon
Aluminum Alloy Treating Co. - Vernon
Aero Aluminum Treating - Vernon

6.6.2 Evaluation: In order to keep hand straightening at a minimum, the following practices should be maintained as much as production facilities and production loads warrants. These practices represent the consensus of opinions of Convair, and of the aluminum heat-treat processors contacted.

6.6.2 Evaluation: (Cont'd)

- (1) During the forming of parts, relatively high pressure equipment should be employed to obtain 5000 to 7500 psi forming pressures.
- (2) Use salt bath for heat-treating all finished formed parts with the exception of oool material.
- (3) Where quantity warrants, use air furnaces and spray quench for 6061 material.
- (4) Hand quench parts where configuration is conducive to warpage during rack or free fall quench.
- (5) Where free fall quenching is used, a drop of one to four feet produces the most satisfactory parts. (Many hand quench operations are in the free fall category.)
- (6) Use air furnaces for parts which are to be worked by re-strike or stretch.
- (7) Maintain quench water under 30°F.
- (8) Dip quench parts in a solution (3 parts kerosene to 1 part trichlorethylene) at -20 to -40°F immountely after water quenching and before refrigeration. (The relatively softer material that results, reduces hand straightening time.)
- ()) Proper racking is of the utmost importance.
 - a. Long and relatively narrow parts should be racked in a vertical position, or as nearly

6.0.2 Evaluation: (Cont'd)

- (9) a. vertical as the length will permit.
 - b. Parts entering the quench water should do so in a manner producing a minimum of resistance.
 - c. Rack parts to obtain maximum air circulation in the furnace and water circulation when entering the quench water.
 - d. Heat-creat operators must be trained to rack parts to reduce distortion from the weight of the part during the heating cycle and from the water impact forces during the quenching.
 - e. If a part distorts during heat-treatment, it should be analyzed to determine the correct racking.
 - f. The heat-treat operator must be flexible and have the desire to change the racking as required to prevent or reduce distortion.
 - g. An active inspection is required to insure that proper racking is achieved.
- (10) Equip air furnace racks with double screen floors, the cottom rack approximately 1-1/2" mesh, 2" to below a second rack of approximately 3/4" mesh.

 The acreens "diffuse the water, reducing the impact of the parts as they strike the water nuring organizar, thereby reducing warrante.

6.6.2 Evaluation: (Cont'd)

- (11) Hand straightening methods should be reviewed with
 the aim of reducing lost motion and obtaining the
 greatest amounts of production from each straightening operation.
- (12) Engineering requirements should be reviewed to determine if straightness requirements could be relaxed. It is possible that in many instances, requirements are more severe than the application actually demands.

6.6.3 Action Taken:

- (1) A Verson Wheelon 6500 psi press is included in the 1961 Capital Budget Brochure for Plant 1. This is in consideration of evaluation of item one, paragraph 5.5.2.
- (2) A recommendation was submitted to the responsible supervision to consider increasing the size of the salt bath, to increase our salt bath heat treat capabilities.
- (3) A project is currently in progress to evaluate dipquenching parts to sup-zero temperatures immediately after water quenching and prior to normal refrigeration. This project is also evaluating double screen floors for rack quenching.
- (4) acking procedures have been reviewed. New racks

- 6.0.3 Action Taken: (Cont'd)
 - (4) have been installed and efforts to rack parts to conform with the best techniques are being followed. A recommendation has been made and drawings have been obtained to include illustrations of recommended racking and handling of parts during quenching in the M.P.S. on aluminum solution heat-treatment.
- 6.7 Problem: Fecent developments in the high energy forming field at Fort Worth have not been assimilated to supplement Convairun Diego's high energy forming development.
 - 5.7.1 Facility Investigated: Convair-Fort Worth (Ref. 7.5).
 - €.7.2 valuation:

Dynapak revelopment is currently centered around determining the ram speed. This is sone by tracing the progress of the advancing ram on a constant speed circulating graph from which milisecond time increments show the ram advance. The graphic results can be readily analyzed and the ram speed calculated. The resulting data is being used to gain more knowledge of the mechanics of tension crack formation, which develops in the extrusion process.

Some tabelar production work is conducted by the Fort forth Hi-Vo-Pak facility. Forming, trimming and piercing is now acted in a single operatio, essentially free of turns. The parts formed are for the E-53 aircraft.

- 6. DEVELOPMENT OF PROTECT: (Cont'd)
 - 6.7.3 Action Taken: Convair-San Diego has some similar parts used on the present production aircraft which are being studied in the light of the Fort North developments.
 - 6.8 <u>Problem:</u> The Kodak Masking Process has not been evaluated as a possible capital investment to supplement chemical milling at Convair-San Diego.
 - 6.8.1 Facility Investigated: Convair-Fort Worth. (Fef. 7.6)
 - 6.8.2 Evaluation: Kodak Metal Etch Resist has proven unsatisfactory at the present state of development. To date, only small 4" x 6" panels have been masked with any degree of success. These panels were made at Eastman Kodak Co. Fort Worth work on larger banels was unsatisfactory. Fin holes in the maskants and limit must which reacted with the etchants allowed the etchant to pit the metal under the maskants. Extensive development work is still required before the process can be applied to production work. Practically no we shad them considered on complex curvature components. In which field the Kodak method would offer the greatest potential.
 - 6.8.3 Action Taken: It was recommended that no capital expenliture ce made at this time because the process is insufficiently developed. It was estimate that even a crash program could not advance this development to a point of expenditure before the next fiscal year.

5. DEVELOPMENT OF PROJECT: (Cont'd)

- 6.9 Problem: Convair-San Diego has not utilized the solutions of industry-wide problems presented at Technical Society Conventions.
 - 6.9.1 Facilities Investigated: SAE Convention in Los Angeles.
 (Ref. 7.7)
 - 6.9.2 Evaluation: From paper presentations attended at the convention, the following potential proposals are under consideration:
 - (1) Use of titanium backup bars for fusion welding to help obtain a narrow weld bead with good uniformity and less workpiece distortion.
 - (2) Use of B.O.B. Chevron joints for thir gauge metal fusion welding. This type joint is self-aligning and has a uniform burn-down which remaits better arc control.
 - (3) Use of a super cooled forch and tamped was to help refine the grain structure in the well time. Amon is passed through liquid nitrogen and reaches the workpiece at about -180°F.
 - (4) The successful fusion welding of foil metals repends in part, on the thermodynamic properties of the welding arc. Variations in work hardening of certain stainless steels, surface scale, height of burn-lown flanges, power input and general non-uniformity of the metal cause arc wandering. These effects should be studied quantitatively.

5. DEVELOPMENT OF PROTECT: (Cont'd)

3.3.2 -valuation:

- (5) Foil seem welding a rapid method of lutt welding on a seam welder.
- (5) Forming of refractory metals in inert atmospheres.
- (7) Development of low cost, see through, plastic inert gas fusion welding chambers.
- (8) Evaluation of methods of lot segregation of refractory metals to be used for forming.
- () Development of hot-riveting of refractory metals.
- (10) Evaluate effect of forming conditions on refractory metals (stressed vs. non-stressed, notch sensitivity, temperature, etc.).
- (11) Evaluate use of titanium and refractory metal alloys as high temperature brazing materials for limitation vacuum brazing dissimilar refractory results.
- 5.3.3 Action Taken: To date, Project Requests have been prepaged to further develop items 6.7.2 - (1.71), 731 e.:

7. FIBLIOGHAPHY:

- 7.1 J. P. Sandich to S. Leith, 20 June 1 200; Trip report, 5-15-00.

 to Convair-Pomona, Colifornia and Colormatic C les Co., Gardera,
 California.
- "A. J. Goods to J. F. Langlois, 25 July 1 80; Trip Report to Kilsty Thre Lambly, Los Anceles, California.
- 7.; Geral. E. Erass spy to S. Meith, a July 1 key report of T in to Converses. Sector time 2 to July 1.

7. BIBLIOGRAPHY: (Cont'd)

- 7.4 L. J. Mattek and E. J. Vermilyea to 3. Leith, 8 August 1960;

 Trip Report to Aluminum Heat-Treat Jobbers and Aircraft Corp.
 in the San Diego and Los Angeles vicinities.
- 7.5 J. F. Murphy to A. P. Langlois, 26 August 1960; Trip Report to Fort Worth.
- 7.6 L. J. Mattek to S. Leith, 20 October 1%0; Trip Report to Convair-Fort Worth, 12-14 October 1960.
- 7.7 E. Vermilyea, W. Carr, J. Lederer and G. Bradbury to S. Leith, 18 October 1960; Trip Report to Los Angeles, SAE Convention.